

2016 BRIDGE INSPECTION REPORT

COMMISSION NUMBER: 15014

ROUTE 58 BUSINESS (RIVER STREET)
OVER
FALL CREEK

STRUCTURE NUMBER: 1901



STRUCTURE INSPECTION REPORT – REGULAR

Agency ID: 1081901-000000000020204 **Date of Inspection:** 01/20/2016

Due: JANUARY		Inspection Frequency: 24 Months	
County/City: CITY OF DANVILLE	Feature Intersected: FALL CREEK		
Main Route: 58 BUSINESS	Facility Carried: RIVER STREET		
Lead Inspector: J. B. HANSEN	Location: 0.07 OLD HALIFAX RD; 0.32 BRYANT AVE.		

Signature of Lead Inspector _____ Signature & Date of City/Town Reviewer _____	PE Stamp of Reviewer
---	----------------------

SPECIAL REQUIREMENTSFracture Critical ☐Fatigue Prone Details ☒Pin & Hanger ☐**CONDITION RATINGS**

Deck: 6
 Superstructure: 6
 Substructure: 6
 Channel/Channel Prot.: 7
 Culvert: N

Capacity Sign R12-1 (Tons): N

Capacity Sign R12-5

Single (Tons): N

Semi (Tons): N

FIELD POSTING

Sign Legibility: N

Sign Visibility: N

Capacity Sign R12-1 (Tons): N

Capacity Sign R12-5

Single (Tons): N

Semi (Tons): N

TRAFFIC SAFETY FEATURES

Bridge Railings: 0

Transitions: 0

Approach Guardrail: 0

Approach Guardrail Ends: 0

YEAR PAINTED 1994**ELEMENT CONDITION STATE DATA**

No.	Description	ENV	Unit	State 1	State 2	State 3	State 4	State 5	Total
*22	Concrete Deck – Rigid Overlay	Low	SF		8422				8422
*92	Reinforced Concrete Sidewalk	Low	LF	256					256
*107	Steel Open Girder – Coated	Low	LF	540	72	208	16		836
*210	Reinforced Concrete Pier Wall	Low	LF	129	2	5			136
*215	Reinforced Concrete Abutment	Low	LF	126	12	2			140
*234	Reinforced Concrete Pier Cap	Low	LF	125	4				129
*286	Slope – Unprotected	Low	EA	2					2
*295	Reinforced Concrete Wingwalls	Low	LF	74					74
*302	Compression Joint Seal	Low	LF	106	6				112
*311	Moveable Bearing	Low	EA	20	4				24
*313	Fixed Bearing	Low	EA	8					8
*334	Metal Bridge Railing	Low	LF			255	1		256
*357	Pack Rust	Low	EA		1				1
*358	Deck Cracking	Low	EA	1					1
*359	Soffit of Concrete Deck	Low	EA		1				1
*363	Section Loss	Low	EA		1				1
*701	Utilities	Low	EA	1		1			2
*702	Drains	Low	EA		1				1
*706	Soffit of Overhang of Concrete Deck	Low	EA				1		1

*-Changes since 01/30/2014

Attachments: Structure Inventory Data Sheet ☒
 Cover Sheet of Rating Calculations ☒

Sketches ☒
 Other ☐

Channel Profile ☒
 Clearance Sheet ☐

Date Printed 3/15/2016

SCHWARTZ & ASSOCIATES, INC.
 CONSULTING ENGINEERS
 Lynchburg-Roanoke, Virginia

Page 2

STRUCTURE INSPECTION REPORT – REGULAR

Agency ID: 1081901-000000000020204

Date of Inspection: 01/20/2016

County/City: CITY OF DANVILLE

Feature Intersected: FALL CREEK

Main Route: 58 BUSINESS

Facility Carried: RIVER STREET

Location: 0.60 MAIN STREET; 8.60 HALIFAX COUNTY

Lead Inspector: J.B. HANSEN

Additional Inspectors: B.A. MOSEBROOK, SET

DESCRIPTION	Three Continuous Steel Multi-Beam Spans with Concrete Deck, 128'-3" total length.	
ORIENTATION	Abutment A on left looking downstream. Spans numbered 1-3 and Piers 1-2 numbered from Abutment A. Beams 1-8 numbered left to right facing Abutment B.	
MISCELLANEOUS (Items which are structure specific and cannot be included in another section.)	★ - Denotes changes since last inspection.	Bridge Coordinates N 36° 35' 12.36" W 79° 22' 44.80"
	Weather at time of inspection: Partly Cloudy, 38° F	
SPECIAL REQUIREMENTS (Special Equipment needed or Special Inspections required such as: Fracture Critical, Underwater, Fatigue Prone, Scour Critical, Moveable Bridge, Segmental Concrete, Pin and Hanger, etc.)	Snooper and traffic control used to access fatigue prone details.	
WORK DONE	None	
STRUCTURAL ANALYSIS	2016 BrR 6.5 LRFR Rating (Controlling member: Beam 2) Type 3 – 53 tons Type 3S2 – 62 tons See attached load rating coversheet.	
OVERALL CONDITION	SATISFACTORY. -Wearing Surface has cracks, scale & aggregate polish. -Expansion Dam at Abutment B has spalled concrete. -Bottom of deck and overhang has delaminated and spalled concrete. -Median and sidewalk has stripped waterproofing. -Sidewalk has cracks. -Railing has peeling paint, corrosion, corroded bolts and impact damage. -Drains are clogged -Waterline in Bay 1 has corrosion and is bowed. -Waterline support at Pier 1 has corrosion with section loss and sags. -Expansion joints filled with debris and leaks. -Bearing devices have corrosion, missing anchor bolts/nuts, and gaps between beams. -Paint system failure on exterior beam fascias, diaphragms, beam bearing areas and bearing assemblies. -Beams 1 and 8 have corrosion and pack rust at splice plates. -Substructure has cracks, scale, delamination, and spalled concrete. -Approach pavement has cracks, is breaking up and has potholes. -Approach guardrail has impact damage.	
RECOMMENDATIONS	-Repair bearing assemblies that have gaps between bearing device and beam. -Replace leaking expansion joints. -Replace failed waterline support in Bay 1 at Pier 1. RECOMMENDATIONS continues on next page.	

STRUCTURE INSPECTION REPORT – REGULAR

Agency ID: 1081901-00000000020204

Date of Inspection:

01/20/2016

**RECOMMENDATIONS
(CONT'D.)**

- Clean, prepare and paint structural steel and railing.
- Repave approach pavement.
- Repair spalled expansion dam at Abutment B.
- Repair delaminated/spalled concrete in bottom of deck, overhang, and substructure.
- Replace corroded and damaged rail posts and corroded railing bolts.
- Replace missing anchor bolts/nuts in bearing devices.
- Replace damaged approach guardrail.
- Clean clogged deck drains.

DECK**Wearing Surface****Condition Rating: 6**

Latex concrete overlay.

Wearing surface has hairline diagonal and transverse cracks as follows:

Lane		Span 1 (LF)	Span 2 (LF)	Span 3 (LF)
EBL	sealed	55	100	75
	unsealed	10	20	10
WBL	sealed	40	170	100
	unsealed	5	25	25

★Wearing Surface has light scale with aggregate polishing over 30% of entire surface.
See Photo #8.

★Expansion dam at Abutment B, right lane of EBL has 1 SF spalled concrete 1" deep.
See Photo #8.

★Expansion dam at Abutment B has D-spalls 1" wide X 1" deep totaling 2 LF.

Top of Deck

Not Visible.

Bottom of Deck

Bottom of deck has areas of delaminated/spalled concrete in isolated locations (up to ½" deep) as follows: Span 1 – 3 SF; Span 2 – 4 SF; Span 3 - 6 SF

Overhang

★Overhang has delaminated/spalled concrete (up to 1" deep) as follows:
Upstream side – 7 SF; Downstream side – 9 SF

Median

Waterproofing worn off of median for 40% of surface area.

Sidewalks

Waterproofing worn off of sidewalk for 40% of surface area.

Sidewalk on downstream side of structure has 6 transverse hairline cracks. Sidewalk on upstream side has 4 transverse hairline cracks.

Underside of sidewalk on both sides of structure has 7 transverse cracks (up to 1/16" wide) and are exhibiting efflorescence.

RailingRailing has peeling paint throughout. **See Photo #9.**

STRUCTURE INSPECTION REPORT – REGULAR

Agency ID: 1081901-00000000020204

Date of Inspection:

01/20/2016

<u>Railing (Cont'd.)</u>	<p>Several railing connection bolts at cantilevered connections on both sides of structure have severe corrosion and up to 30% section loss.</p> <p>★ Railing post at Abutment B is twisted 3/4" x full height with one flange bent 3/4" x 9".</p> <p>★ 4th Railing post from Abutment A has previous corrosion with 75% section loss on lower 4" with a 2" X 4" corrosion hole at connection to bracket support. See Photo #10.</p>
<u>Drains</u>	★ Two (2) scuppers on the upstream side are clogged.
<u>Utilities</u>	<p>Waterline bowed up 1' above support located 10' from Abutment A in Bay 1. See Photo #11</p> <p>Waterline at Abutment A encroachment has heavy corrosion and 1/8" pitting on bottom. See Photo #12.</p> <p>Waterline support in Bay 1 of Span 2 at Pier 1 is failing (sagging) due to severe section loss in web of channel. Large corrosion holes are present.</p>
<u>Expansion Joints</u>	<p>Expansion joints are partially filled with dirt and debris.</p> <p>★ Expansion joint material is leaking at Abutment A EBL for 3 LF and Abutment B EBL for 3 LF. See Photo #8.</p>

SUPERSTRUCTURE	Condition Rating: 6
<u>Bearings Devices</u>	<p>Masonry plates have up to 1/4" deep pitting due to previous corrosion.</p> <p>Bearing devices at abutments and piers have light to medium rust.</p> <p>Bearing devices for Beams 2 and 3 at Abutment A each have one missing anchor bolt.</p> <p>Bearing device for Beam 7 at Abutment A is missing 4 anchor bolt nuts.</p> <p>Bearing device for Beam 2 at Pier 2 has a 1/4" gap between rocker bearing and masonry plate.</p> <p>Bearing devices for Beams 1-3 at Abutment B have up to 1/16" gap between rocker bearing and masonry plate.</p>
BEAMS	FATIGUE PRONE DETAILS
	<p>NOTE: Hands on inspection of Fatigue Prone Details performed this inspection. Condition of Fatigue Prone Details considered in the general condition rating of Superstructure. See sketch for details.</p> <p>All riveted connections - Category D. <i>No deficiencies found.</i></p> <p>Utility support fillet weld to web of beam – Category E. <i>No deficiencies found.</i></p> <p>Utility support flange to flange fillet weld – Category C'</p>

STRUCTURE INSPECTION REPORT – REGULAR

Agency ID: 1081901-00000000020204

Date of Inspection:

01/20/2016

<p><u>General</u></p> <p><u>Diaphragms</u></p> <p>PAINT</p>	<p><i>No deficiencies found.</i></p> <p>★Beams 1 and 8 have light rust along flanges and web throughout lengths.</p> <p>★Beams 1 and 8 have up to 1/4" pitting in web 4" high x 1" wide adjacent to sidewalk support brackets at numerous locations throughout lengths.</p> <p>★Beam 1 splice, 1st from Pier 1, has up to 3/8" pack rust between plate and bottom flange.</p> <p>★Beam 8 splice, 2nd from Pier 1, has up to 1/2" pack rust between plate and bottom flange. See Photo #13.</p> <p>Sidewalk channel beams on upstream and downstream side of structure in Spans 1-3 have heavy rust scale on top flange, which has lifted sidewalk up to 3/8" at random locations.</p> <p>★Sidewalk channel beams on upstream and downstream side have 1/8" deep pitting adjacent to railing posts pitting up to full height of web x 1/2" wide due to previous corrosion.</p> <p><i>No deficiencies found.</i></p> <p>Light to medium rust on isolated areas of structural steel at abutments and piers.</p> <p>★Beams have isolated areas of peeling paint totaling approximately 5% of area.</p>
<p>SUBSTRUCTURE ABUTMENTS</p> <p><u>Wings</u></p> <p><u>Backwalls</u></p> <p><u>Bearing Seats</u></p> <p><u>Breastwall</u></p>	<p>Condition Rating: 6</p> <p>★Wingwall on downstream side of Abutment B has a hairline vertical crack 6 LF long.</p> <p>Backwall at Abutment A has 6 full-height vertical cracks (up to 1/16" wide). Backwall at Abutment B has 5 full-height vertical cracks (up to 1/16" wide).</p> <p>Top of backwall at Abutment A has 22 cracks (up to 1/16" wide). Top of backwall at Abutment B has 31 cracks (up to 1/16" wide).</p> <p>Waterline encroachment in Abutment A backwall in Bay 1 has heavy moisture seepage onto breastwall.</p> <p>Backwall at Abutment B in Bay 6 has 2 S.F. of spalled/delaminated concrete (up to 3/4" deep) with exposed reinforcing steel and 60% section loss in rebar.</p> <p><i>No deficiencies found.</i></p> <p>Breastwall at Abutment A has 2 full height vertical cracks up to 1/16" wide.</p> <p>Breastwall at Abutment B has 3 full height vertical cracks up to 1/16" wide with efflorescence.</p> <p>★Breastwall at Abutment B, Bay 7, has 2 SF of delaminated concrete.</p>

STRUCTURE INSPECTION REPORT – REGULAR

Agency ID: 1081901-00000000020204

Date of Inspection:

01/20/2016

PIERS	<u>Weep Holes</u>	Weep holes at both abutments filled with dirt and debris.
	<u>Footings</u>	Not Visible.
	<u>Undermining</u>	No deficiencies found.
	<u>Settlement</u>	No deficiencies found.
	<u>Caps</u>	Cap at each pier has one full height hairline vertical crack. ★Cap at Pier 1, upstream end, Span 2 side has 4 SF of delaminated/spalled concrete (1/2" deep). Cap at Pier 2 has heavily scaled concrete on upstream end.
	<u>Walls</u>	Wall at each pier has one full height hairline vertical crack. ★Pier walls have light scale along lower 3'. Wall at Pier 1, upstream end has 4 SF of delaminated/spalled concrete (2" deep) with exposed reinforcement (20% section loss). See Photo #14 Wall at Pier 2 has heavily scaled concrete and 1 SF of delaminated/spalled concrete (1" deep) with exposed reinforcement (20% section loss) on upstream end and 2 SF on downstream end.
	<u>Footings</u>	No deficiencies found.
	<u>Undermining</u>	No deficiencies found.
	<u>Settlement</u>	No deficiencies found.

CHANNEL AND SLOPE PROTECTION	Condition Rating: 7
<u>Channel</u>	Channel Profile checked this inspection and no significant change found since 01/27/2010. See attached channel profile sketch.
<u>Scour</u>	No deficiencies found.
<u>Embankment Erosion</u>	No deficiencies found.

STRUCTURE INSPECTION REPORT – REGULAR

Agency ID: 1081901-000000000020204	Date of Inspection: 01/20/2016
---	---------------------------------------

<u>Drift</u>	No deficiencies found.
<u>Vegetation</u>	No deficiencies found.
<u>Adequacy of Opening</u>	Sufficient

FIELD POSTING	
<u>Actual Posting</u>	Not posted.
<u>Legibility</u>	N/A
<u>Visibility</u>	N/A
<u>Advanced Warning Signs</u> (In accordance with Traffic Engineering Division Memorandum TE-244 dated 5-7-94)	N/A

OTHER	
APPROACH PAVEMENT	Approach pavement at Abutment A is cracked 1/4" wide and breaking up for 20 SF adjacent to backwall with 4 SF of potholes (2" deep). See Photo #15. ★ Approach pavement at Abutment B is cracked 1/4" wide and breaking up for 30 SF ★ Approach median is 3" low at Abutment B.
TRAFFIC SAFETY FEATURES	
<u>Bridge Railing</u>	Substandard.
<u>Transitions</u>	Substandard.
<u>Approach Guardrail</u>	Substandard. ★ Approach guardrail on upstream side of Abutment A has 20 LF of impact damage.
<u>Approach Guardrail Terminal</u>	Substandard.
OBJECT MARKERS	Object markers (Type 3) in place at Abutment A (WBL) run-on end of structure on upstream side.



PHOTO #1

Approach elevation looking from Abutment A to Abutment B.



PHOTO #2

Approach elevation looking from Abutment B to Abutment A.



PHOTO #3
Side elevation looking upstream.



PHOTO #4
Side elevation looking downstream.



PHOTO #5
General view of pier.



PHOTO #6
General view of abutment.



PHOTO #7

Sealed cracks in wearing surface, westbound lane, Span 2. Note scale.



PHOTO #8

Spalled concrete in expansion dam and leaking expansion joint at Abutment B.



PHOTO #9
Peeling paint on railing.



PHOTO #10
Corrosion on 4th railing post from Abutment A.



PHOTO #11
Waterline is bowed above support, Bay 1.



PHOTO #12
Corrosion and pitting in waterline, Abutment A.



PHOTO #13
Pack Rust on Beam 8 splice.




PHOTO #14
Spalled concrete on Pier 1 wall, upstream end.



PHOTO #15

Approach pavement at Abutment A is cracked, breaking up and has potholes.



ELEVATION VIEW

Looking Downstream

Checked 2016 - No significant changes
JBH

YEAR	POINT							
	A	B	C	D	E	F	G	H
2014	14.5'	19.5'	---	---	---	22.4'	19.3'	16.9'
2012	NO MEASUREMENT TAKEN							
2010	14.8'	19.2'	30.2'	29.6'	30.2'	24.1'	19.1'	17.1'

Scale:

Horizontal - 1" = 19.358'

Vertical - 1" = 19.68'

Measurements taken from top of railing
at upstream face of structure.



701 FIRST STREET, S.W.
ROANOKE, VIRGINIA 24016
(540) 345-9342
FAX (540) 345-7891

UPSTREAM PROFILE - ROUTE 58 BUS.
(RIVER STREET) OVER FALL CREEK

BRIDGE NO. 1901

CITY OF DANVILLE, VIRGINIA

Calc'd By: MLF

Chk'd By: DKA



Inspection Date:

30-JANUARY-2014


Sheet No.:

CH1


Fatigue Prone Details



1. CATEGORY D
ALL RIVETED CONNECTIONS



2. CATEGORY E
UTILITY SUPPORT -
FILLET WELD TO
WEB OF BEAM



3. CATEGORY C'
UTILITY SUPPORT -
FLANGE-TO-FLANGE
FILLET WELD


Rte: 58 Business (River Street)
Over: Fall Creek
City: Danville
Struct. No.: 1901
Cadd Ref.: 1081901
Page No.: 1

Structure and Bridge

LOAD RATING SUMMARY FORM FOR STRUCTURES

Rte.: 58 (River Street)
 Over: Fall Creek
 VA Structure No.: 1901
 FED. ID: 000000000020204
 City: Danville
 District: Lynchburg
 Rated By: PLJ Date: 2/16/16
 Checked By: APS Date: 2/16/16
 VDOT Reviewer: _____

PE Seal



Adam Summers
 2016.02.16 15:52:44 -05'00'

CALCULATION TOOLS AND METHOD USED: Bridge Rating 6.5 (LRFR)
 BASIS FOR RATING:

	GVW (TONS)	RATING FACTOR	CONTROLLING MEMBERS	CONTROLLING LOCATION	CONTROLLING FORCE
DESIGN LOAD					
HL-93 (INV)	N/A	1.044	Beam 2	Pier 1	Flexure
HL-93 (OPR)	N/A	1.353	Beam 2	Pier 1	Flexure
		TONS			
HS-20 (INV)	36	48	Beam 2	Mid Span 2	Flexure
HS-20 (OPR)	36	62	Beam 2	Mid Span 2	Flexure
LEGAL LOADS		TONS			
VA Type 3	27	53	Beam 2	Mid Span 2	Flexure
VA Type 3S2	40	62	Beam 2	Pier 2	Flexure
*LANE	40	81	Beam 2	Pier 1	Flexure
PERMIT LOAD		TONS			
BP-90	45	77	Beam 2	Pier 2	Flexure
BP-115	57.5	84	Beam 2	Pier 1	Flexure
SH VEHICLES		TONS			
NRL:	40	49	Beam 2	Mid Span 2	Flexure
SU4:	27	44	Beam 2	Mid Span 2	Flexure
SU5:	31	47	Beam 2	Mid Span 2	Flexure
SU6:	34.75	47	Beam 2	Mid Span 2	Flexure
SU7:	38.75	49	Beam 2	Mid Span 2	Flexure

*Not applicable for single spans less than and equal to 200 feet.

'ON' RECORD INVENTORY - Federal Items

Agency ID. : 1081901-000000000020204
Maint. Resp. : 108

SR: 75.80

SD/FO : ND

Bridge Key: 000000000020204

Identification	
State (1)	: 51 Virginia
District (2)	: Lynchburg
Facility Carried (7)	: River Street
Feature Intersected (6)	: Fall Creek
Record Type (5A)	: Route On Structure
Level of Service (5C)	: 1 Mainline
Directional Suffix (5E)	: 0 N/A (NBI)
Latitude (16)	: 36° 35' 12.36" ✓
Longitude (17)	: 79° 22' 44.80" ✓
Struc Num (8)	
Location (9)	
Rte. Signing Prefix (9B)	
Route Number (5D)	
Place Code (4)	
County Code (3)	
Mile Post (11)	
Border Br. Code (9A)	
% Responsibility (9B)	
Border Bridge No. (99)	

Structure Type and Materials	
No. Spans Main Unit (46)	: 3
Main Span Material (43A)	: 4 Steel Continuous
Main Span Design (43B)	: 2 Stringer/Girder
Deck Type (107)	: 1 Concrete-Cast-in-Place
Membrane (108B)	: 0 None
No. Appr. Spans (46)	: 0
Appr. Span Material (44A)	: 0 Other
Appr. Span Design (44B)	: 00 Other (NBI)
Wearing Surface (108A)	: 3 Latex Concrete/Similar
Deck protection (108C)	: 0 None

Age and Service		
Year Built (27)	: 1948	: -1
Type of Service On (42A)	: 5 Highway-pedestrian	
Type of Service Under (42B)	: 5 Watervay	
Lanes On (28A)	: 4	: 0
Detour Length (19)	: 1.88	
ADT (29)	: 18,000 ✓	: 2012 2014
% Truck ADT (109)	: 6.7	

Geometric Data	
Length Max Span (48)	: 55.00' ✓
Curb/Sidewalk Width Left (50A)	: 4.27' ✓
Width Curb to Curb (51)	: 54.00'
Appr. Roadway Width (32)	: 54.00'
Stew (34)	: 30.00" ✓
Horizontal Clearance (47)	: 54.00'
Vertical Clearance (10)	: 99.99'
Minimum Vertical Clearance Over Bridge (53)	: 99.99'
Minimum Vertical Underclearance Reference (54A)	: N Feature not hwy or RR
Minimum Vertical Underclearance (54B)	: 0.00'
Minimum Lateral Underclearance Reference Right (55A)	: N Feature not hwy or RR
Minimum Lateral Underclearance Right (55B)	: 0.00'
Minimum Lateral Underclearance Left (56)	: 0.00'

	Inspection			
Regular Inspection	FREQ (91)	LAST INSP. (90)	NEXT INSP.	
	24	01/30/2014	01/30/2016	
Fracture Critical	REQ'D (92)	LAST INSP. (93)	NEXT INSP.	
	: N	-1		
Undewater Insp.	: N	-1		
Other Special Insp	: N	-1		

Classification	
Toll Facility (20)	3 On free road
Functional Class (26)	14 Urban Other Princ
Historical Significance (37)	5 Not eligible for NRIHP
Parallel Structure (101)	No // bridge exists
Temporary Structure (103)	Not Applicable (P)
Nat. Truck Network (110)	1 Part of natl network
National Base Net (12)	1 LRS Inv Rte (13a)
	Fed. Maint. Resp. (21)
	Owner (22)
	Defense Highway (100)
	Direction of Traffic (102)
	Highway System (104)
	NBIS Length (112)
	Long Enough
	Sub# (13)
	00

Condition	
Deck (59) : 6 Satisfactory	Superstructure (59): 6 Satisfactory
	Substructure (60) : 6 Satisfactory
	Culvert (62) : Not Applicable
	Channel/Channel Protection (61): 7 Minor Damage

Load Rating and Posting		
Design Load (31)	: 4 H 20	
Oper. Rig. Method (53)	: 1-LF-Load Factor	3
Inv. Rig. Method (55)	: 1-LF-Load Factor	3
Posting (70)	: 5 At/Above Legal Loads	
	Posting Status (41)	: A Open, no restriction
	Oper. Rig. (64)	: 52.5- 62
	Inv. Rig. (66)	: 37.7 48

Appraisal	
Bridge Rail (36A)	: 0 Substandard
Transition (36B)	: 0 Substandard
Appr. Rail (36C)	: 0 Substandard
Appr. Rail Ends (36D)	: 0 Substandard
Appr. Rail Ends (36D)	: 0 Substandard
Scour Critical (113)	: 5 Stable w/in footing
Deck Geometry (68)	: 4 Tolerable
Undercr., Vert. and Horiz. (69)	: N Not applicable (NB)
Waterway Adequacy (71)	: 7 Above Minimum
Approach Alignment (72)	: 5 Above Tolerable
Su. Evaluation (67)	: 6

Proposed Improvements					
Type of Work (75)	: Not Applicable (P)	Improv. Length (76)	: 0.00	Future ADT (114)	: 19,500
Bridge Cost (94)	: \$0.00	Year of Estimate (97)	: 2014	Yr. of Fut. ADT (115)	: 2035
Roadway Cost (95)	: \$-	Total Cost (96)	: \$0.00		

Navigation Data		
Navigation Control 38	: Permit Not Required	
Vertical Clearance 39	: 0.00	Horizontal Clearance 40 : 0.00
Pier Protection 111	: Not Applicable (P)	Lift Bridge Vertical Clearance 116 : :

Federal 'On' Record Inventory Report

Wed 01/20/2016 14:00:40

'ON' RECORD INVENTORY - State Items

Agency ID : 1081901-00000000020204
Maint. Resp. : 108

Bridge Key: 00000000020204

Bridge Inventory

VA Str. Number (S4) : 1901
Residency Code (S1) : Halifax - 18
Jurisdiction Code (S2) : Danville - 108
Adj. Juris. Code (S10) :
Map Location (S195) :
Alt Location (S193) :
Parallel Structure (S192) :
Repl. Structure (S38) : N Does not Replace
Special Codes (S12) : P
Special Structure Code (S173) :
Sketch Page Number (S172) :
Original Plan Number (S13a) : 089-20
Original Std. Plan Number (S13b) :
Recon. Plan Number (S14a) :
Recon. Stand. Plan No (S14b) :
Railroad Mile Post (S191) :

Ratings

Design Load High (S44) : 4 H 20
Stress Level (S47) : M-Mid-Range
Stress Analysis Meth (S48) : M-Fed-LF-State-Ws
Computer File Name (S49a) : 1081901
Last Run Date (S49b) : 2/16/2016
Rated Capacity (Single) (S45) : 49-53
Rated Capacity (Semi) (S46) : 57-62
Posted Status (S50) :
Posting Required (S55) : M No Maintenance Req'd
Posted Date (S51) : 11/14/2013
Foot Bridge Posting (S169) :

Construction and Maintenance

Year Reconstructed (S27) : 0
Type Construction (S39) : N - Bridge
Type Reconstruction (S40) :
Year Last Painted (S94) : 1994
Paint System (S186) : A
Project Status Code (S189) :
Project UPC Code (S58) : 0
HBRP Indicator (S41) : N Not Applicable
Maint. Resp. - State (S15) : Danville - 108

Hydraulics

Scour Critical Ind (S30) : N No Study Required
Scour Critical Remark (S31) :
Height of Opening (S24) : 0
Drain Barrel Length (S25) : 0
Drain Depth of Fill (S26) : 0
Total Indicator (S42) :
Number Drain Openings (S22) : 0
Drainage Area (S194) :
Drain Width (S23) : 0

Appurtenances (S196)

Sign : N Sound Wall : N Ped. Fence : N

Special Equipment (S64)

Ladder : Y ManLift : N Scaffold : N
Snooper : Y Bucket Truck : N Rigging : N
Boat : N Portoon : N Platform Truck : N

Utilities (S190)

Water : Y Sewer : N Lighting : N
Gas : Y Cable : N Fiber Optic : Y
Electric : N Phone : N Other : N

Substructure Layout (S19, S20, S21)

Abutment A	Material	Design Type	Abutment B	Material	Design Type
Material and Type	1 Concrete	04 Curtain Wall	Material and Type	1 Concrete	04 Curtain Wall
Fnd/Piles Mat/Type	3 Firm Material	01 Spread Footing	Fnd/Piles Mat/Type	3 Firm Material	01 Spread Footing
Main Pier - Group 1; Count	2	01 Solid	Appr. Pier - Group 1; Count	0	01 Spread Footing
Fnd/Piles Mat/Type	1 Solid Rock	01 Spread Footing	Fnd/Piles Mat/Type		
Main Pier - Group 2; Count	0		Appr. Pier - Group 2; Count	0	
Material and Type			Material and Type		
Fnd/Piles Mat/Type			Fnd/Piles Mat/Type		
Main Pier - Group 3; Count	0		Appr. Pier - Group 3; Count	0	
Material and Type			Material and Type		
Fnd/Piles Mat/Type			Fnd/Piles Mat/Type		
Main Pier - Group 4; Count	0		Appr. Pier - Group 4; Count	0	
Material and Type			Material and Type		
Fnd/Piles Mat/Type			Fnd/Piles Mat/Type		
Main Pier - Group 5; Count	0		Appr. Pier - Group 5; Count		
Material and Type			Material and Type		
Fnd/Piles Mat/Type			Fnd/Piles Mat/Type		

Roadway

VA Highway System Code (S185) : Primary
On Under Code (F5A) : 1
Lane of Route (S5) :
HTRIS Route Number (S8) :
HTRIS Node Number (S7) : 0
HTRIS Node Offset (S9) : 0.00
RNS Location :
Latitude : 36.5567665667
Longitude : -79.3791111111

Inspection

Inspection Key : EVOS
Posted Capacity Std. (S52) :
Posted Capacity Single (S53) :
Posted Capacity Semi (S54) :
Posting Sign Leg. (S170) :
Posting Sign Vis. (S171) :
Critical Features Class (S62) :
Maint. Repair Cost (\$1000) (S56) : \$ 0
Maintenance Fund Code (S57) : U Urban

Critical Recommendations

Outstanding Critical Recommendation (S176) :
Prev. Comp. Critical Recommendation (S179) :

Clearances On Structure

Roadway Width - Single/Left (S33) : 26.00
Roadway Width - Right (S34) : 26.00
Median Width (S35) : 4.00